MEASUREMENT BOOK

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
	Certificate:						
1.	This is certified that the contractor has done the work satisfactorily.						
2.	certified that all debrises are removed from workplace						
3.	There is no departmental issue to the contractor.						
	8/2/2018						
	Sladanga ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು ಟಿ.ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ ಬೆಂಗಳೂರು						8/2/18

Scanned by CamScanner

Audited and admitted for Rs. 4805190-00
Passed by Cheque for Rs. 4641916-00

M. A. R. 57 (Rule 116) **No. D**

Measurement Book

62119

Serial No. .....

Name of work ..... From ..... To .....

Name of Contractor of nature of Agency.....

Date of commencement of work.....

by ad... 163974-00

Accounts Officer Exe. Engineer

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
	Manjunatha Nagara main road						
	Vitrified tiles laying						
	(Rough)						

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಟಿ.ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

08/12/18

Scanned by CamScanner